

# Historic Structure Reports & Steeple Assessments Overview

Malcolm (Mac) Collins, AIA, LEED AP, NCARB

Ellen Angel, NCARB, LEED AP Artifex A/E



## Housekeeping

- Feel free to have your video camera on or off if your connection is unstable, turning it off may help
- Please be on mute when not speaking
- You can ask questions using the chat feature during the presentation or wait until Q&A pauses and then unmute and ask it!

## **Speakers**

- Malcolm (Mac) Collins, AIA, LEED AP, NCARB
- Ellen Angel, NCARB, LEED AP, Artifex A/E

# The Academy Hall



Malcolm Collins, AIA



August 1st, 2020





# Project Team





ELLEN ANGEL, NCARB Principal In Charge





R. MICHAEL PULLEN, AIA Project Manager



MALCOLM COLLINS, AIA Historic Preservationist



SCOTT C. HOMER, PE Structural Engineer



JASON BEAULIEU, PE Mechanical Engineer



KYLA MAGNUSSON

DESIGN ASSOCIATES

PATRICK GUTHRIE, AIA

# Team Role Matrix





| USM ACADEMY HALL WORK SCOPE                                  | elle Arch | AAC COLLIF | MICE PULLE | COTTHON | ASON BEAU | ARRICK CH | THREE STANDARD | 11550 <sup>14</sup> |   |                      |
|--|-----------|------------|------------|---------|-----------|-----------|----------------|---------------------|---|----------------------|
| 1. EXISTING BUILDING REVIEW AND ASSESSMENT                   |           |            |            |         |           |           |                |                     |   |                      |
| Historic Analysis  |           |            |            |         |           |           |                |                     |   |                      |
| Building Elements and Systems                                |           |            |            |         |           |           |                |                     |   |                      |
| Exterior Envelope Assessment                                 |           |            |            |         |           |           |                |                     |   |                      |
| Causes of Deterioration                                      |           |            |            |         | •         |           |                |                     |   |                      |
| Conditions Assessment  |           |            |            |         |           |           |                |                     |   |                      |
| Review of Applicable State, Federal, and Local Ordinances    |           | •          |            |         |           |           |                |                     |   |                      |
| Pr   |           | _          |            |         |           |           |                |                     |   | Responsible          |
| 2. RECOMMENDATIONS FOR CORRECTIVE ACTION                     |           |            |            |         |           |           |                |                     | _ | Shared Responsibilit |
| Rehabilitation Strategy for Interior and Exterior            |           |            | •          |         |           |           |                |                     |   | Shared Nesponsibilit |
| Sustainable Preservation                                     |           |            |            |         |           |           |                |                     |   | Support              |
| Zoning, Planning, and Historic Commission Revies             |           |            |            |         |           |           |                |                     |   |                      |
| Recommendations for preservation, rehabilitation, and repair |           |            |            |         |           |           |                |                     |   |                      |
| Preservation Treatment and Use                               |           |            |            |         |           |           |                |                     |   |                      |
|  |           |            |            |         |           |           |                |                     |   |                      |
| 3. PRIORITIZATION, PROBABLE COST, POSSIBLE FUNDING           |           |            |            |         |           |           |                |                     |   |                      |
| Building and Life Safety Code Review                         |           |            |            |         |           |           |                |                     |   |                      |
| Prioritization of Work                                       |           |            |            |         |           |           |                |                     |   |                      |
| Estimate of Probable Cost                                    |           |            |            |         |           |           |                |                     |   |                      |
| Identify Funding Sources                                     |           |            |            |         |           |           |                |                     |   |                      |
| Construction Phasing   |           |            |            |         |           |           |                |                     |   |                      |
| PROJECT MANAGEMENT/TEAM COORDINATION                         |           |            |            |         |           |           |                |                     |   |                      |
| Project Management and Team Coordination                     |           |            |            |         |           |           |                |                     |   |                      |
| Renderings and Support graphics                              |           |            |            |         |           |           |                |                     |   |                      |



#### State Historic Preservation Office



- Identify + nominate eligible properties to the National Historic Register
- Conduct comprehensive surveys + maintain inventory of historic properties
- Prepare + implement a statewide historic preservation plan, administer state programs of Federal assistance
- Provide public information, education, training and technical assistance
- Work with local governments in the development of local historic preservation programs and help them become "certified local governments"



MAINE HISTORIC
PRESERVATION
COMMISSION



## Code Review




The Maine Uniform Building + Energy Code (MUBEC)

codes and standards that apply to the Academy Building:

- 2015 International Building Code (IBC)
- 2015 International Existing Building Code (IEBC)
- z2009 International Energy Conservation Code (IECC)
- ASHRAE 62.1-2013 Ventilation for Acceptable Indoor Air Quality
- ASHRAE 90.1-2013 Energy Standards for Buildings except Low-Rise Residential Buildings







## Historical Overview



First Euro-American Settlers Arrive in Gorham——1736

Gorham Granted Township — 1764 -

1803

Gorham Academy

Construction Completed, First Students — 1806.

Women Accepted into Program — 1807


Boys Under Age 10 Accepted — 1813


Large Growth and Expansion: Female ——1835 - 1895 Seminary Created and destroyed by fire.

Closure due to creation of Public Schools — 1877

Western Normal School 1878

Building Leased to the State of Maine 1909 for 999 Years







## Historical Overview

1916

1978



Academy Building converted to house Industrial Arts (IA) Program

Institution name changes: —— 1965-1970


Gorham State College Gorham State College of the University of Maine University of Maine at Portland-Gorham

IA Program moves, Academy Building — 1966 used for art instruction

University of Southern Maine

Continued use as art instructional space — 1978-present

ADA bathroom renovations — 2013







## Historical Overview




#### John Calvin Stevens Renovation - 1909

- Stevens is one of Maine's most notable architects.
- His work helped restore the Academy Building, which by 1909 had fallen into disrepair (below)










## Existing Conditions: Interior





#### Basement




## Existing Conditions: Structure





#### Foundation













## Existing Conditions: Interior





#### First Floor














## Existing Conditions: Interior





#### Second Floor










## Existing Conditions: Structure





#### First Floor and Second Floor








## Existing Conditions: Structure





#### **Roof Framing**











## Existing Conditions: HVAC





- The main HVAC system includes
  - 2 energy recovery ventilators
  - 2 natural gas boilers
  - 1 hot water expansion tank
- Current ventilation insufficient
- Boilers are approximately 10 years old and in good condition.
- Hot water heaters and insulated piping were installed in 2013 and remain functional

## Existing Conditions: Exterior





North Elevation



South Elevation



West Elevation



**East Elevation** 

#### **Character Defining Features**














## **Academy Building Lease Agreement**

of Southern Maine must maintain the Academy Building's architectural, historical, and cultural value. This can be achieved through...

**Preservation or Rehabilitation** 







# Secretary of the Interior's Standards and Guidelines for the Treatment of Historic Properties

- Preservation
- Rehabilitation
- Restoration
- Reconstruction







**Preservation** is defined as "the act or process of applying measures necessary to sustain the existing form, integrity, and materials of an historic property."

- Maintenance and repair of historic materials rather than replacement
- Limited upgrading of MEP systems for code-required work and functionality
- Does not include new exterior additions





Historic Preservation of storefronts at Yukon Gold Rush National Historic Park (photos courtesy of *NPS*)





**Rehabilitation** is defined as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural or architectural values."

- Modifications and additions are sensitive to building form and materials
- MEP upgrades should have minimal impact on character-defining features





Rehabilitation projects with sensible additions (photos courtesy of NPS)

Rehabilitation is the method of treatment recommended by the Project Team





## Secretary's Standards for Rehabilitation

- Use and Occupancy must be similar
- Historic character will be retained and preserved
- Cannot misrepresent historical development (style, additions, etc.)
- Distinctive materials or construction techniques will be preserved
- Features will be repaired rather than replaced.
   Replaced features will match in looks and material (when possible).



Replaced windows that damage historic character



Replaced column base that matches looks and material (photos courtesy of *NPS*)





- Chemical or physical treatments will be non-damaging
- Archeological resources will be protected and preserved in place
- New additions or alterations must be differentiated from and not affect historical character
- New additions or alterations, if reversed, must leave the essential form and integrity of building unimpaired.



Graffiti removed from historic building with poultice




Bricks damaged from sandblasting (photos courtesy of NPS)


# Front Façade











# Front Façade
















# Front Façade
















## Project 1a


# Front Façade







Gable face and details, flashing, trim, some roofing, porch rails and details, soffit, building siding and painting above second floor



## Front Façade






**Project 1a Cost:** \$93,300



Gable face and details, flashing, trim, some roofing, porch rails and details, soffit, building siding and painting above second floor



## Project 1b


## Front Façade







Porch columns, base, capitols, and details; remove and reset granite; repair foundation; new wood steps; and siding repair and painting below second floor



### Project 1b

## Front Façade





## **Project 1b Cost:** \$92,195



Porch columns, base, capitols, and details; remove and reset granite; repair foundation; new wood steps; and siding repair and painting below second floor



# Siding Restoration
















## Siding Restoration




## **Project 2 Cost:** \$84,600











## Foundation Restoration











## Foundation Restoration






## **Project 3 Cost:** \$36,300











# Roof + Cupola Restoration














## Roof + Cupola Restoration




## **Project 4 Cost:** \$49,500










## Elevator / Stair / ADA








## Elevator / Stair / ADA






## **Project 5 Cost:** \$413,700





## Interior Stairwell









## Interior Stairwell



## **Project 6 Cost-** \$80,600





## **Q & A**

## Malcolm L. Collins AIA, LEED AP

Maine Licensed Architect
Architectural, Historic Preservation & Planning Concepts
Post Office Box 152
South Freeport, Maine 04078
207.865.0346
mlcarch@comcast.net

# **Upcoming Events**



#### Historic Preservation Easements Wednesday, December 9, 2020

4:00 PM 5:00 PM

Join Maine Preservation's Ali Barrionuevo for an introduction to preservation easements and Maine Preservation's Protect & Sell program. You'll learn what a preservation easement is, how an easement agreement protects a building, and how Maine Preservation's Protect & Sell program works to preserve Maine's historic resources.

Sign up: <a href="https://www.mainepreservation.org/webinars-and-educational-programs">https://www.mainepreservation.org/webinars-and-educational-programs</a>





**THANK YOU** 

SUPPORT OUR MISSION:
HTTPS://WWW.MAINEPRESERVATION.ORG/GIVE